

# Intel® Chipset Device Software

## 10.1.18793.8276

### Release Notes

---

*June 16th, 2021*

**Microsoft Windows\* 10 x86(only for Intel® Atom™ / Celeron®/ Pentium® Processor)**

**Microsoft Windows\* 10 x64**

**Microsoft Windows\* Server 2019 x64**

**Microsoft Windows\* Server 2016 x64**

**Microsoft Windows\* Server 2012R2 x64**

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request. Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Code names featured are used internally within Intel to identify products that are in development and not yet publicly announced for release. Customers, licensees and other third parties are not authorized by Intel to use code names in advertising, promotion

The Intel® Chipset Device Software may contain design defects or errors described as "known issues" which may cause the product to deviate from expected performance. Current characterized known issues are documented in this update.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and other countries.

\*Other names and brands may be claimed as the property of others.

Copyright © 2021, Intel Corporation. All rights reserved.

## Revision History

Date	Driver Revision	Description	Build Number
Jun 16, 2021	10.1.18793.8276	PV	18793.8276
May 13, 2021	10.1.18739.8272	PV	18739.8272
Mar 29, 2021	10.1.18711.8263	PV	18711.8263
Mar 16, 2021	10.1.18698.8258	PV	18698.8258
Jan 7, 2021	10.1.18634.8254	PV	18634.8254
Dev 15,2020	10.1.18593.8250	PV	18593.8250
Nov 24,2020	10.1.18460.8229	PV	18460.8229
July 18,2020	10.1.18460.8229	PV	18460.8229
May 30,2020	10.1.18412.8219	PV	18412.8219
May 7,2020	10.1.18383.8213	PV	18383.8213
Apr 15, 2020	10.1.18340.8203	PV	18340.8203
Feb 4, 2020	10.1.18295.8201	PV	18295.8201
Jan 7, 2020	10.1.18267.8194	PV	18267.8194
Jan 3, 2020	10.1.18263.8193	PV	18263.8193

## Intel® Chipset Device Software Support

Driver version	Minor version	Description (supported products)
10.1.43	4	11 <sup>th</sup> Gen Intel® Core™ (Tiger Lake)
10.1.42	8	Intel (R) VT-d Registers Intel (R) RAS Registers Intel (R) Mesh 2 PCIe Registers Intel (R) PMON MSM Registers Intel (R) MSM Registers Intel (R) NTB Registers Intel (R) DDRIO Host Config Registers Intel (R) CHA ALL0 Registers Intel (R) CHA ALL1 Registers
10.1.41	5	11 <sup>th</sup> Gen Intel® Core™ (Rocket Lake)
10.1.34	10	Intel® 500 Series Chipset Family (Tiger Lake PCH-H)
10.1.33	5	Intel® 400 Series Chipset Family
10.1.32	3	Intel(R) LPC Controller Intel(R) P2SB Intel(R) PMC Intel(R) SPI (flash) Controller Intel(R) PCI Express Root Port Intel(R) Shared SRAM
10.1.31	2	Intel® 400 Series Chipset Family
10.1.30	3	10 <sup>th</sup> Gen Intel® Core™ (Comet Lake)
10.1.29	4	Intel(R) LPC Controller Intel(R) P2SB Intel(R) PMC Intel(R) SPI (flash) Controller Intel(R) PCI Express Root Port Intel(R) Shared SRAM

10.1.28	2	Intel(R) LPC Controller Intel(R) P2SB Intel(R) PMC Intel(R) SPI (flash) Controller Intel(R) PCI Express Root Port Intel(R) Shared SRAM
10.1.27	4	Intel(R) On-Package Platform Controller Hub
10.1.25	5	Intel(R) LPC Controller Intel(R) P2SB Intel(R) PMC Intel(R) SPI (flash) Controller Intel(R) PCI Express Root Port Intel(R) Shared SRAM
10.1.24	5	11 <sup>th</sup> Gen Intel® Core™ (Tiger Lake)
10.1.22	3	Intel® 495 Series Chipset Family
10.1.20	3	10 <sup>th</sup> Gen Intel® Core™
10.1.16	7	Intel(R) 300 Series Chipset Family
10.1.16	7	Intel(R) C240 Series Chipset Family
10.1.15	6	Mobile 8 <sup>th</sup> Gen Intel® Core™ processor family
10.1.14	8	8th Gen Intel(R) Core™
10.1.13	3	Intel(R) Celeron(R)/Pentium(R) Processor
10.1.12	3	Intel(R) 495 Series Chipset family
10.1.11	4	Intel(R) 200 series chipset family
10.1.11	4	Intel(R) 300 series chipset family
10.1.10	5	Intel(R) Xeon(R) processor E3-1200 v6 product family
10.1.10	5	7th Generation Intel(R) Core(TM) processor family
10.1.7	3	Intel(R) Xeon(R) processor E3-1500 v5 product family
10.1.7	3	Intel(R) Xeon(R) processor E3-1200 v5 product family
10.1.7	3	6th Generation Intel(R) Core(TM) processor family
10.1.6	2	Intel(R) 100 Series chipset
10.1.6	2	Intel(R) C230 series chipset family
10.1.5	3	7th Generation Intel(R) Core(TM) processor family
10.1.5	3	6th Generation Intel(R) Core(TM) processor family

## New Features

Features Added in Build 10.1.18793.8276	
ID	Description
1	[10.1.5.3] certified for 21H2
2	[10.1.6.2] certified for 21H2
3	[10.1.7.4] certified for 21H2
4	[10.1.9.3] certified for 21H2
5	[10.1.10.5] certified for 21H2
6	[10.1.11.4] certified for 21H2
7	[10.1.12.3] certified for 21H2
8	[10.1.13.3] certified for 21H2
9	[10.1.14.8] certified for 21H2
10	[10.1.15.7] certified for 21H2
11	[10.1.16.8] certified for 21H2
12	[10.1.17.1] certified for 21H2
13	[10.1.20.3] certified for 21H2
14	[10.1.22.3] certified for 21H2
15	[10.1.24.6] certified for 21H2
16	[10.1.25.5] certified for 21H2
17	[10.1.27.4] certified for 21H2
18	[10.1.28.2] certified for 21H2
19	[10.1.29.4] certified for 21H2
20	[10.1.30.3] certified for 21H2
21	[10.1.31.2] certified for 21H2
22	[10.1.32.3] certified for 21H2
23	[10.1.33.3] certified for 21H2
24	[10.1.34.10] certified for 21H2; Fixed DMA exemption list
25	[10.1.41.5] certified for 21H2
26	[10.1.42.8] certified for 21H2
27	[10.1.43.4] certified for 21H2; Fixed DMA exemption list
Features Added in Build 10.1.18739.8272	
ID	Description
1	None
Features Added in Build 10.1.18711.8263	
ID	Description
1	None
Features Added in Build 10.1.18698.8258	
ID	Description
1	[10.1.43.3] made public
Features Added in Build 10.1.18634.8254	
ID	Description
1	[10.1.34.8] made public
Features Added in Build 10.1.18614.8253	
ID	Description
1	[10.1.42.7] Changed platform name to Server_Common;
Features Added in Build 10.1.18593.8250	
ID	Description
1	[10.1.41.5] made public
Features Added in Build 10.1.18460.8229	
ID	Description
1	[10.1.24.5] made public
Features Added in Build 10.1.18412.8219	
ID	Description
1	None
Features Added in Build 10.1.18383.8213	
ID	Description

1	[10.1.12.3] certified for 20h1
2	[10.1.14.8] certified for 20h1
3	[10.1.20.3] certified for 20h1
4	[10.1.22.3] certified for 20h1
5	[10.1.27.4] certified for 20h1
6	[10.1.28.2] certified for 20h1
7	[10.1.30.3] certified for 20h1
8	[10.1.31.2] certified for 20h1
9	[10.1.33.3] certified for 20h1
<b>Features Added in Build 10.1.18340.8203</b>	
ID	Description
1	none
<b>Features Added in Build 10.1.18295.8201</b>	
ID	Description
1	[10.1.28.2] made public
2	[10.1.5.3] certified for 19h2
3	[10.1.10.5] certified for 19h2
4	[10.1.14.8] certified for 19h2
5	[10.1.30.3] added 9B54, and 9B64. Certified for 19h2
<b>Features Added in Build 10.1.18267.8194</b>	
ID	Description
1	[10.1.20.3] added
2	[10.1.22.3] added
<b>Features Added in Build 10.1.18263.8193</b>	
ID	Description
1	[10.1.30.2] Made public, certified.
2	[10.1.31.2] Made public, certified, updated SKUs for LPC Controller devices.
3	[10.1.33.3] Updated SKUs for LPC Controller devices.

## Installer update

<b>Changes in Installer version 3.1.7.143</b>	
ID	Description
1	none
<b>Changes in Installer version 3.1.7.131</b>	
ID	Description
1	none
<b>Changes in Installer version 3.1.7.130</b>	
ID	Description
1	none
<b>Changes in Installer version 3.1.7.128</b>	
ID	Description
1	MUP3.0 support
<b>Changes in installer version 3.1.7.127</b>	
ID	Description
1	Make extension infs install by installer - change logic to install many infs for single HWID with restriction: inf files must be from different folders.
<b>Changes in Installer version 3.1.7.121</b>	
ID	Description
1	Removed supported platform list from readme
2	Programs and Features (ARP) entry for Chipset INF will always have English product name. Before name was localized during installation and looked bad when OS changed display language.
<b>Changes in Installer version 3.1.7.120</b>	
ID	Description
1	Readme.txt shows Package version and Installer version
<b>Changes in Installer version 3.1.7.118</b>	

ID	Description
1	Update MUP.xml file with error code 350 mapped to REBOOT_UPDATE_PENDING
<b>Changes in Installer version 3.1.7.117</b>	
ID	Description
1	Added Fix for CVE-2019-14596
<b>Changes in Installer version 3.1.7.107</b>	
ID	Description
1	Added -ignoreid switch
2	Updates in custom action logging
<b>Changes in Installer version 3.1.7.100</b>	
ID	Description
1	fixed NDA readme file installed by Public package, now Public package installs correct readme file.
<b>Changes in Installer version 3.1.7.99</b>	
ID	Description
1	Fixed "the messy code is displayed during install chipset on Arabic OS"
<b>Changes in Installer version 3.1.7.98</b>	
ID	Description
1	CSVer.dll removed from package
2	Security fixes
3	MUP extract and extract functions fixed
4	Added Add Remove Programs entry function
5	Added uninstall functionality, does not uninstall drivers – only package contents (license, readme, registry keys, AddRemove programs entry)
6	Installation fails with known error code on unsupported platform
<b>Changes in Installer version 3.1.7.90</b>	
ID	Description
1	MUP packages have DriverFiles folder complying to MUP path requirements - \production\<os_name>\<os_arch> Also supports Windows10S requirement (raw driver files in package)
2	Supports Windows10S requirement (raw driver files in package)
3	MUP 2.4.5 compliant
4	Please note WiX framework used to build installer got updated to 3.11.1 which contains security fixes
<b>Changes in Installer Version 3.1.7.89</b>	
ID	Description
1	Tweaked previous fix implementation for: Thunderbolt [TBT] power flow issue while re-applying PCIe controller inbox – added devcon disable/enable functionality Before inf installation devcon is used to: - disable root TBT devices (device IDs as found in table in HSD – device parent must not be a TBT device), - task is scheduled in Task Scheduler, - task runs on OS startup and uses devcon to enable the same root TBT device, then the task removes itself. –devcon switch, usage example –devcon c:\tools\devcon.exe <b>Note: without an externally supplied devcon the function won't work.</b>
<b>Changes in Installer Version 3.1.7.88</b>	
ID	Description
1	Thunderbolt [TBT] power flow issue while re-applying PCIe controller inbox – added devcon disable/enable functionality - Before inf installation devcon is used to disable TBT devices , then a task is scheduled in Task Scheduler; task runs on OS startup and uses devcon to enable the same devices twice with timeout in-between, then the task removes itself. - –devcon switch, usage example –devcon c:\tools\devcon.exe without an externally supplied devcon the function won't work - –devcontimeout switch, usage example –devcontimeout 10 sets how long to wait in seconds in-between enables
<b>Changes in Installer Version 3.1.7.86</b>	
ID	Description
1	Added –exclude switch - '–exclude usb' will not install any inf file that has USB in it's name